

Recommandation pour le choix des gants

	Solvant	Acide	Base
Latex	Acetone Methyl alcohol Ethyl alcohol Butyl alcohol THF NMP Acetonitrile Toluene	Acetic acid Citric acid Chlorhydric acid Nitric acid	Calcium acetate Potassium acetate NH ₃ KOH NaOH KHCO ₃ NaHCO ₃
Nitrile	Petroleum ether Hexane Diethyl oxide Propyl alcohol Chloroform Cyclohexane Xylene CCl ₄ DMSO Ethyl acetate Dichloromethane	Oxalic acid Phosphoric acid	Ethylamine Methylamine Diethylamine
Néoprène	Acetonitrile DMF DMSO	Chlorhydric acid Formic acid Sulfuric acid	

■ Très bien

■ Bien

■ Résistance limitée